

Software Update for Motorola CLIQ XT™ (1.32.20)

Introduction

This update provides improvements to the phone's performance.

For optimal performance, we encourage you to download and install this latest software update.

For more information on your Motorola CLIQ XT™, visit us <http://www.motorola.com/mycliqxt>.

Who Can Use This Release

ALL Motorola CLIQ XT™ users.

Highlights

After downloading and installing the software, you will notice the following improvements:

Overall Phone Performance	Users will notice a significantly improved overall performance and responsiveness to input requests, including: opening applications, answering calls, opening the Happenings widget, and downloading attachments and pictures within email
Additional Stability	Improved stability, resulting in fewer occurrences of unresponsiveness and/or programs quitting unexpectedly
Bluetooth® Performance	Improved performance and connectivity with other Bluetooth devices
Messaging	Prevents erroneous notifications that a message has not been sent. Also resolves MMS sending / receiving functionality issues in certain scenarios
Touchscreen	Improved touch screen sensitivity and touch response
SWYPE® Keyboard	Includes updates to the latest version of the SWYPE software, resulting in improved overall performance of the application

Instructions for Installing Software

1. We recommend downloading the update over Wi-Fi or 3G (with a fully charged battery and active SIM card installed in your phone).
2. Follow these steps to update your T-Mobile Motorola CLIQ-XT™:
 1. Upon receipt of the notification message, select **Download**.
 2. After the software is downloaded, select **Install now**.
 3. After the software is installed, your phone will re-start automatically.

If you have difficulty with this update, visit us at <http://www.t-mobile.com/Contact> or <http://www.motorola.com/mycliqxt>.

There is no charge for this update other than your usual data connection costs.

Certain features, services and applications are network dependent and may not be available in all areas; additional terms, conditions and/or charges may apply. The software functionality and features provided by a specific version of the Android operating system may vary. Contact your service provider for details. MOTOROLA and the Stylized M Logo are registered in the US Patent & Trademark Office. The MOTOBLUR Logo is a trademark of Motorola. The Bluetooth trademarks are owned by their proprietor and used by Motorola, Inc. under license. All other trademark and

product or service names are the property of their respective owners. © 2010 Motorola Mobility Inc. All rights reserved.